

FEDERAL AVIATION ADMINISTRATION AIRWORTHINESS DIRECTIVES

LARGE AIRCRAFT BIWEEKLY 2021-03

1/18/2021 - 1/31/2021



Federal Aviation Administration
Continued Operational Safety Policy Section, AIR-141
P.O. Box 25082
Oklahoma City, OK 73125-0460

CHANGE OF ADDRESS NOTICE

Any change of address regarding the biweekly service must include the mailing label from a recent issue or your name and address printed exactly as they appear on the mailing label (including the computer number above the address).

Please allow one month for an address change.

MAIL YOUR ADDRESS CHANGE TO:

Superintendent of Documents
Government Printing Office
Mail List Branch SSOM
Washington, DC 20402

Telephone: (202) 512-1806
Facsimile: (202) 512-2250

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E – Emergency; COR – Correction; R – Replaces, A – Affects

Biweekly 2021-01

2020-25-06		Bombardier, Inc.	BD-100-1A10
2020-25-13		CFM International, S.A.	LEAP-1A23, LEAP-1A24, LEAP-1A24E1, LEAP-1A26, LEAP-1A26CJ, LEAP-1A26E1, LEAP-1A29, LEAP-1A29CJ, LEAP-1A30, LEAP-1A32, LEAP-1A33, LEAP-1A33B2, LEAP-1A35A
2020-26-04	R 2013-18-08	The Boeing Company	737-100, -200, -200C, -300, -400, and -500
2020-26-07	R 2019-23-05 A 2010-26-05	Dassault Aviation	MYSTERE-FALCON 900
2020-26-08		The Boeing Company	787-8, 787-9, and 787-10
2020-26-09		The Boeing Company	737-100, -200, -200C, -300, -400, and -500
2020-26-11		Airbus SAS	A300 F4-605R and A310-324
2020-26-12		Gulfstream Aerospace LP	G280
2020-26-15	R 2016-07-14	Airbus SAS	A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-211, -212, -214, -216, -231, -232, and -233; A321-111, -112, -131, -211, -212, -213, -231, and -232
2020-26-18		Airbus SAS	A330-243, -343, and -941
2020-26-20		Airbus Canada Limited Partnership	BD-500-1A10 and BD-500-1A11
2020-26-21		Airbus SAS	A350-941

Biweekly 2021-02

2021-01-03		International Aero Engines AG	V2500-A1, V2522-A5, V2524-A5, V2525-D5, V2527-A5, V2527E-A5, V2527M-A5, V2528-D5, V2530-A5, V2531-E5, and V2533-A5;
2021-02-05		Airbus SAS	A330-201, A330-202, A330-203, A330-223, and A330-243; A330-223F and A330-243F; A330-301, A330-302, A330-303, A330-321, A330-322, A330-323, A330-341, A330-342, and A330-343; A330-841; A330-941; A340-211, A340-212, and A340-213; A340-311, A340-312, and A340-313; A340-541; A340-642

Biweekly 2021-03

2021-01-02		M7 Aerospace LLC	SA26-AT and SA26-T
------------	--	------------------	--------------------



AIRWORTHINESS DIRECTIVE

www.faa.gov/aircraft/safety/alerts/
www.gpoaccess.gov/fr/advanced.html

2021-01-02 M7 Aerospace LLC: Amendment 39-21378; Docket No. FAA-2020-0910; Project Identifier 2018-CE-044-AD.

(a) Effective Date

This airworthiness directive (AD) is effective February 26, 2021.

(b) Affected ADs

None.

(c) Applicability

This AD applies to M7 Aerospace LLC Model SA26-AT and SA26-T airplanes, all serial numbers, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 61, Propellers/propulsors.

(e) Unsafe Condition

This AD was prompted by reports of the airplane power lever linkage detaching from the TPE331 engine propeller pitch control (PPC) shaft. The FAA is issuing this AD to address detachment of the power lever linkage to the TPE331 engine PPC shaft, which could result in uncommanded change to the engine power settings with consequent loss of control.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) PPC Lever Inspection

(1) Within 100 hours time-in-service (TIS) after the effective date of this AD and thereafter at intervals not to exceed 100 hours TIS, inspect the security of the PPC lever by pulling the PPC lever upward by hand to ensure it does not detach from the PPC input shaft. If the PPC lever detaches during any inspection, before further flight, comply with paragraphs (h) and (i) of this AD.

(2) The replacement/re-identification required by paragraph (h) of this AD and the installation of the secondary retention feature (safety wire) required by paragraph (i) of this AD terminate the repetitive inspections of the PPC lever attachment required by paragraph (g)(1) of this AD.

(h) Replace and Inspect the PPC Assembly

Within 600 hours TIS after the effective date of this AD or within 12 months after the effective date of this AD, whichever occurs first, unless required before further flight by paragraph (g)(1) of this AD, do the actions in either paragraph (h)(1) or (2) of this AD in accordance with the Accomplishment Instructions in Honeywell International Inc. Service Bulletin TPE331-72-2190, dated December 21, 2011, except you are not required to report information to the manufacturer.

(1) Replace the PPC assembly with the applicable new design PPC assembly.

(2) Inspect the splined end of the shouldered shaft for the presence and condition of a threaded hole and, before further flight, repair or replace the cam assembly or rework the PPC assembly, as necessary, and re-identify the shouldered shaft.

(i) Secondary Retention Feature (Safety Wire)

Before further flight after completing the actions required by paragraph (h) of this AD, install the secondary retention feature (safety wire) on the airplane PPC lever and the PPC assembly.

Note 1 to paragraph (i): Paragraph j. of M7 Aerospace SA26 Series Maintenance Manual Temporary Revision 4-02, dated July 22, 2020, contains information related to installation of the secondary retention feature (safety wire).

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Safety Management Section, Small Airplane Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k)(1) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(k) Related Information

For more information about this AD, contact Jonas Perez, Aerospace Engineer, Fort Worth ACO Branch, FAA, 10101 Hillwood Parkway, Fort Worth, Texas 76177-1524; phone: 817-222-5145; fax: 817-222-5960; email: jonas.perez@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(3) The following service information was approved for IBR on May 5, 2017 (82 FR 15982, March 31, 2017).

(i) Honeywell International Inc. Service Bulletin TPE331-72-2190, dated December 21, 2011.

(ii) [Reserved]

(4) For Honeywell service information identified in this AD, contact Honeywell International Inc., 111 S 34th Street, Phoenix, Arizona 85034-2802; phone: 855-808-6500; email: AeroTechSupport@honeywell.com; internet: <https://aerospace.honeywell.com/en/services/maintenance-and-monitoring>.

(5) You may view this service information at FAA, FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call 816-329-4148.

(6) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on December 28, 2020.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-01332 Filed 1-21-21; 8:45 am]